

R
52

5φ

800

7700

840

7900

7100

5700

485

2800

B = 2840

40

J = 2250³

2700

3450

5500

Handwritten notes on the right side of the diagram:
6500
7800
7400
8200
8200